DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT 77424 P30956

Date of Maintenance 6~8:2	Reason for Maintenar	nce:	4,12,11	10 75
Property Address: 47 Elec	green Rp	Property Owner's Name:	Todd Road	5
	- Lohe State	Zip Code G	EO Code/Property I.D.#:	
Vhat was done to thing? Tank(s) Pumped		interpretation in the	espoidaselle d'engra	
Sludge and soum measured.	Liquid Lev	el of Tarik in. Sluc	dge Level in. Scum Le	evel in
Do tanks need to be pumped? Yes No (If no provide me	easurements) Total (Slud	ge + Scum) / Liquid	Level = %Sludge &	& Scum
1. Access used to remove septage:	The second secon	Other (Go to #3 below)	* Tank must be pumpe	-
2. If maintenance hole was used, were	all covers securely replac	ed? Yes No please	is greater than 25%.	and Applied
Explanation:				
If owner refuses to allow a Subsur them complete and sign the follow	face Sewage Treatment : ving statement:	System (SSTS) to be pumpe	d through the maintenance	hole, have
l,		to to allow the		
hole. I understand that removal of so	olids and liquids through a	ther access naines is seen	olids and liquids through the m	naintenance
4. Is the tank designed as a leaky tank?	example: seepage pit. cesso	ool drovell leaching nie	sidered maintenance.	
Tank#1 Yes No Verificatio		out ary trent leaching pit		Ť
Tank#2 Yes No Verification	3			
5. Is there evidence of soul leading	Method Used:	1		
5. is there evidence of tank leakage fro damaged, cracked, or structurally u	om a septic, holding, pre nsound maintenance hol	treatment or pump tank be	low the operating depth or	evidence of
Tank	Leaking Out	Leaking In	ı.	
Septic/Holding Tank#		Yes No	Cover Damage	
Septic/Holding Tank#		Yes No	Yes No	
Pretreatment Tank	Yes No	Yes No	Yes No	•
Pump Tank	Yes No	Yes No	Yes No	
6. How many gallons of septage were re	emoved?		Yes No	
Tank#1 / Tank#2 / Tank#2	Pretreatment		mp Tank	
7. Other information: List any troublesh	ooting, minor repairs co	nducted, tank safety conce	ns, or other concerns.	
B. Certification: I hereby certify as a State and made the observation	of Minnesota certified SS	S Maintainer that I personall others in the performance of	y conducted the work	
Maintainer's Name: Olson's Sewer Servi	an enectry supervised (ner's Address: 17638 Lyons S	this job.	
Maintainer's License #: 216 Ma	. 585	64-2082	- CEST TAKE, MIN	
Maintainer's Signature	V-	Date:	-8-23	
Ja ()	10			