DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT C755 (4 3000

Date of Maintenance 6/12/23	Reason for Maintenance		C/356# 3	0958
Property Address: 284 Laure	1 Road	Property Owner's Name:	Ken Dreck-tra	.,
Municipality: Mantomedi			EO Code/Property I.D. #:	ch
A A William Clother Street Control	As first part and the second part of the second par			
Tank(s) Pumped		syleasur e ments invista	មនុស្សារដ្ឋារូបបានប្រើប្រ	ini prijeza
Sludge and soum measured.	Liquid Level o	of Tarik in. Slu	dge Level in. Scum Le	Day of London
Do tanks need to be pumped?	11		Juni D	evel in
Yes No (If no provide measure	ements) Total (Sludge	+ Scum) / Liquid	d Level = % Sludge	& Scum
1. Access used to remove septage: Ma	nintenance Hole Otl	ier (Go to #3 below)	* Tank must be pump	ed if this value
2. If maintenance hole was used, were all co	overs securely replaced?	XI Yes TINO please	is greater than 25%.	to this while
Explanation:		The Thense	expiain	
3. If owner refuses to allow a Subsurface them complete and sign the following	Sewage Treatment Svs	tem (SSTS) to be number	dat A .a	
them complete and sign the following	statement:	tem (3313) to be pumpe	d through the maintenance	hole, have
l, ·	(owner's name), refuse	to allow the removal of c	olids and liquids through the r	
hole. I understand that removal of solids a	ma independ tritoficit Of DE	If access hoints is not can	olids and liquids through the r	naintenance
4. Is the tank designed as a leaky tank? exam	ple: seepage pit, cesspool	drywell. leaching nit	sidered maintenance.	
Tank#1 Yes Wo Verificatio Meth		, and the same of		
Tank#2 Yes No Verificatio Meth				
5. Is there evidence of tank leakage from a	sontic halding musture			•
is there evidence of tank leakage from a damaged, cracked, or structurally unsou	nd maintenance hole c	atment or pump tank be overs?	elow the operating depth or	evidence of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ◯ No	Yes No		
Septic/Holding Tank #2	Yes No	Yes No	Yes No	
Pretreatment Tank	Yes No	Yes No	Yes No	•
Pump Tank	☐Yes ☐No	Yes No	Yes No	
6. How many gallons of septage were remov		Ties Tino	Yes No	
Tank#1 //) 50 Tank#2 //) 5	Pretreatment Ta	m.t.		
111			mp Tank	
7. Other information: List any troubleshooting	ng, minor repairs condu	icted, tank safety conce	rns, or other concerns.	
8. Certification: I hereby cortificate a factor	•			
8. Certification: I hereby certify as a State of M and made the observations, or	innesota certified SSTS Nor directly supervised other	laintainer that I personall	y conducted the work	
Maintainer's Name: Olson's Sewer Service, In		377		
Ad-1	ner's Phone #: 651-464	's Address: 17638 Lyons S	Street NE, Forest Lake, MN	
	/ 03 (-404	2002	·	
Maintainer's Signature		Date:		