PERALIMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance	6/16/23	Reason for Maintenance:			
Property Address:	3540 Nol	UN AUP N	Property Owner's Nam	e:	
	andiq		Code <u>55073</u>	GEO Code/Property I.D. #:	_
Wiltverd	Calcula esy	建 制度转音的	Daniye ko takun k	les and over the second	91 E 1990 X
Tank(s) Pumped	25) 25 ay 25 25 35 (127 26) 25 (27 26) 25)				
Sludge and scum n	easured.	Liquid Level o	f Tarik in. S	udge Level in. Scum Level	
Do tanks need to b	e pumped?	Total (Sludge	Soum!	***	
Yes No (I		emens)		id Level = %Sludge & Scu	m
1. Access used to remove	re septage: 💍 Ma	aintenance Hole Oth	er (Go to #3 below)	* Tank must be pumped if	this val
2. If maintenance hole v	as used, were all c	overs securely replaced?	Atres Tinonlegs	is greater than 25%.	
Explanation:	8		La vas and preusi	: Ехріцііі	
3. If owner refuses to a them complete and s	low a Subsurface ign the following:	Sewage Treatment Syst	em (SSTS) to be pump	ped through the maintenance hole	, have
I, ·	_				
hole. I understand that	removal of solids:	and liquids through othe	to allow the removal of	solids and liquids through the maint	enance
4. Is the tank designed as	a leaky tank? exam	pile: seenae nit cessool	decess points is not co	nsidered maintenance.	
			uryweii, leaching pit		
Tank#1 Yes N	verificatio Metr	nod Used: Vysua/			
Tank#2 Yes AN	Verificatio Meth	od Used: Lisual	•		
Is there evidence of ta damaged, cracked, or s	nk leakage from a	septic, holding, pretres	itment or pump tank	below the operating depth or evid	ence of
	Tank	Leaking Out	Leaking In	1	
Septic/F	lolding Tank #1	☐ Yes ⊠No		Cover Damage	
the state of the s	olding Tank #2	Yes No	Yes No	Yes - No	
Pretreat	nent Tank	Yes No	Yes No	Yes No	
Pump Ta	nk .	Yes No	Yes No	Yes No	
6. How many gallons of se	ptage were remov	1	Thes Missi	Yes PNo	
	Tank #2 1000	Pretreatment Tai		Pump Tank 225	
7. Other information: List :	ny troubleshooti	ng, minor repairs condu	cted, tank safety cond	erns, or other concerns.	
8. Certification: I hereby ce	rtify as a State of M the observations, o	Ninnesota certified SSTS Nor directly supervised other	laintainer that I person	ally conducted the work	_
Maintainer's Name: Olson			•	s Street NE, Forest Lake, MN	
Maintainer's License #: 21	6 Maintai	iner's Phone #: 651-464-			_
Maintainer's Signature	ult	L	Date:	116/22	
	7			14/13	