GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

09305,31373

SSTS MAINTENANCE REPORT

Date of Maintenance	Reason for Maintenance	V N/11097:	Mainten	an D
Property Address: 9924 No	orth Shore Trai	Property Owner's Name	: Copia 11-1	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
Municipality: forest Lake	State and Zi	%/	GEO Code/Property I.D.#:	
de William Voltania				
Tank(s) Pumped			a sombligation do not	流鸣
Sludge and scum measured.	Liquid Level	of Tark in. Slu	idge Level in. Scum	Level i
Do tanks need to be pumped? Yes No life provide means	Total (Sludge	1 Saura)		
13 110 (IT NO PROVIDE MEdisur	emens)		id Level = % Sludg	e & Scum
1. Access used to remove septage: Mi	aintenance Hole 🔲 Ot	ner (Go to #3 below)	* Tank must be pum	ped if this valu
2. If maintenance hole was used, were all c	overs securely replaced?	Nes TNo please	is greater than 25%	6.
Explanation:			unpresss	
3. If owner refuses to allow a Subsurface them complete and sign the following:	Sewage Treatment Sve	tom (SSTS) to be		
them complete and sign the following	statement:	tem (3313) to be pump	ed through the maintenance	e hole, have
b <u></u>	(owner's name), refuse	to allow the removal of		
hole. I understand that removal of solids a			solids and liquids through the	: maintenance
4. Is the tank designed as a leaky tank? exam	ple: seepage pit, cesspool	drywell, leaching pit	isidered maintenance,	
Tank#1 Yes No Verificatio Meth		1		
	- 1-7 MW			
Tank#2 Yes No Verificatio Meth	od Used: 1500			(Get
Is there evidence of tank leakage from a damaged, cracked, or structurally unsou	septic, holding, pretre	atment or pump tank b	elow the operating depth o	r evidence of
Tank	Leaking Out	Leaking In	9.0	
Septic/Holding Tank #1	Yes No	☐ Yes ☑ No	Cover Damage	-
Septic/Holding Tank #2	Yes No	Yes No	Yes No	•
Pretreatment Tank	Yes No	Yes No	Yes No	
Pump Tank	Yes No	Yes No	☐Yes ☐No ☐Yes ☒No	
6. How many gallons of septage were remove	red?		Lies Mills	
Tank#1 1500 Tank#2 1000	Pretreatment Ta	nk n.		
		, ,	Imp Tank 500	
7. Other information: List any troubleshooting	ry, minor repairs condi	icted, tank safety conce	rns, or other concerns.	
B. Certification: I hereby certify as a State of M and made the observations of	innocata continue decre			
and made the observations, or	r directly supervised other	laintainer that I personal ers in the performance of	ly conducted the work	
Maintainer's Name: Olson's Sewer Service, In			, ,	
Melan			Street NE, Forest Lake, MN	
=1/1/	ner's Phone #: 651-464-	2082	1	
Maintainer's Signature	2	Date:	20 62	
Control of the contro			40/21	