## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## **SSTS MAINTENANCE REPORT**

7 1/1/	0	INCE REPORT		
Date of Maintenance / / / Reason for		xeul	7	
Property Address: 18480			3:11 RosenThat	_
Municipality: S	tate MZip Code	55025 GEO C	ode/Property I.D. #:	_
What was done to the system?	Tank Meas	urements (must be co	ompleted if tanks NOT pumped)	
Tank(s) Pumped Sludge and scum measured. Do tanks need to be pumped?	Liquid Level of Tank	The second section of the second seco	Decays List (A. 19. 19. 19. 19. 19. 19. 19. 19. 19. 19	*
Yes No (If no provide measurements)			* Tank must be pumped if this value	
1. Access used to remove septage: Maintenan	ce Hole 🔲 Other (G	o to #3 below)	is greater than 25%.	1)
2. If maintenance hole was used, were all covers se	curely replaced?	Yes No please exp	lain	
Explanation:				
3. If owner refuses to allow a Subsurface Sewag them complete and sign the following statem		(SSTS) to be pumped	through the maintenance hole, have	-
l, (own	er's name), refuse to a	llow the removal of sol	ids and liquids through the maintenance	7
hole. I understand that removal of solids and liq			N 150	
4. Is the tank designed as a leaky tank? example: se	epage pit, cesspool, dry	well, leaching pit		
Tank#1 Yes No Verificatio Method Us	ed:		s	
Tank#2 Yes No Verificatio Method Us	sed:			
5. Is there evidence of tank leakage from a sept damaged, cracked, or structurally unsound m			low the operating depth or evidence	of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	Yes No	Yes No	
Septic/Holding Tank #2	Yes No	Yes No	Yes No	
Pretreatment Tank	Yes No	Yes No	Yes No	
Pump Tank	☐ Yes  1No	Yes No	Yes No	
6. How many gallons of septage were removed	?			
Tank #1 \Soo Tank #2 \lood Pretreatment Tank Pump Tank \lood				
7. Other information: List any troubleshooting,	minor repairs condu	cted, tank safety cond	erns, or other concerns.	
8. Certification: I hereby certify as a State of Minr and made the observations, or d				
Maintainer's Name: Hassle Free Septic	Maintaine	r's Address: P.O. Box 70	2 North Branch, MN 55056	
Maintainer's License #: L3287 Maintaine	r's Phone #: 763-222		7 111	
Maintainer's Signature M77		Date:	7-14-16	