GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance	Reason for Maintenance	_ V52U	DY31241	
Property Address: 23140 Me	clarie Tax	Property Owner's Name	Steve schan	1
Municipality:			30191	rach
2. Witwiston (Miery Com			EO Code/Property I.D.#:	
Tank(s) Pumped		ayen wenen kinura	asomilia: Elemente de m	
Sludge and soum measured. Do tanks need to be pumped?	Liquid Level		dge Level in. Scum Leve	el
Yes No (If no provide measur			d Level = %Sludge & S	cum
7. Access used to remove septage: Minimal Mini	aintenance Hole 🗍 Ot	her (Go to #3 below)	* Tank must be pumped	if this valu
2. If maintenance hole was used, were all c	overs securely replaced	Yes No please	is greater than 25%.	1010
Explanation:				
3. If owner refuses to allow a Subsurface them complete and sign the following:	Sewage Treatment Sys	tem (SSTS) to be pumpe	ed through the maintenance by	
them complete and sign the following:		72		
	(owner's name), refuse	to allow the removal of s	olids and liquids through the ma	intenance
hole. I understand that removal of solids a	and and a middell offli	ST BECESS DOINTS IS NAT PAR	sidered maintenance.	menance
4. Is the tank designed as a leaky tank? exam		, drywell, leaching pit		
Tank#1 Yes No Verificatio Meth	nod Used:			
Tank#2 Tyes No Verificatio Meth	od Used:			
Is there evidence of tank leakage from a damaged, cracked, or structurally unsou	septic, holding, pretre	atment or pump tank b	elow the operating depth or ev	idence of
Tank	Leaking Out	Leaking In		-CHEC VI
Septic/Holding Tank #1	Yes No		Cover Damage	
Septic/Holding Tank #2	☐Yes ☐No	Yes No	Yes	
Pretreatment Tank	☐Yes ☐No	Yes No	Yes No	
Pump Tank	☐ Yes ☐ No	Yes No	Yes No	
6. How many gallons of septage were remov		E III	[] Yes No	
Tank#1 1 Ll Tank#2	Pretreatment Ta	nt _		
7. Other information: List now trouble to			mp Tank 400	
7. Other information: List any troubleshooting	g, minor repairs condu	icted, tank safety conce	rns, or other concerns.	
8. Certification: Thereby cartify as a Sente of Ma				
8. Certification: I hereby certify as a State of M and made the observations, or	innesota certified SSTS N directly supervised other	flaintainer that I personall	y conducted the work	
Maintainer's Name: Olson's Sewer Service, In		's Address: 17638 Lyons		
Bdo7.			pureet NE, Forest Lake, MN	
	ner's Phone #: 651-464-	2082	1	
Maintainer's Signature	13-	Date:	27-23	