

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	6/26/2023 Reason	for Maintenance: _	Routine		
Property Address: _52	52 Trading Post S	Property Owner's Name:		lary Tschida	
Municipality:	ZIP: 5500	)1 Property Ider	ntification Number:	<u> </u>	
Maintenance Permit N	o: <i>\</i>	Maintainer Name an	d License No. Sch	lomka Service LLC	C/L2989
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
▼ Tank(s) Pumped		Liquid Level of Tank in			
Printed Charles Marking Add Add Statement		Sludge Level in Tank in Scum Level in Tank in			
□ Sludge and scum measured     Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage:   Maintenance Hole  Other (enter authorization code)					
<ol> <li>Were all covers securely replaced?</li></ol>					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	Yes No Some answers un	Yes No known. Pumped thro	Yes No	
	Septic/Holding Tank #2	<del>□ Yes □ No</del>	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4 How many gallons	of septage were removed	1?			
Tank #1 1500 gal Tank #2 1000 gal Pretreatment tank gal Pump Tank gal					
	: List any troubleshooting				
Some answers unknown. Pumped through inspection pipe.					
-		2			
6. Location of septage disposal: Metro MCES WWTP					

Schlomka Services, LLC 1904 Vermillion St. Hastings, MN 55033 License# 2989 P: 651-459-3718