GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

	Reason for Maintenance	<u>U953</u>	6431285	
Property Address: 20030 0 c	cinnell Aug	Property Owner's Name	Robert Bousen	
Municipality: Scardia	State Zi	p Code 6		
and a Winter of the Control of the C		Character School State	SEO Code/Property I.D. #:	-
Tank(s) Pumped			a completion and the con-	
Sludge and scum measured. Do tanks need to be pumped?	Liquid Level	, 310	dge Level in. Scum Level	
Yes No (If no provide measur			d Level = %Sludge & Scu	ım
1. Access used to remove septage:	aintenance Hole Ot	her (Go to #3 below)	* Tank must be pumped if	this sal
If maintenance hole was used, were all of Explanation:	covers securely replaced	Yes No please	is greater than 25%. explain	ri 112 (9)
· · · · · · · · · · · · · · · · · · ·				
3. If owner refuses to allow a Subsurface them complete and sign the following	Sewage Treatment Sys statement:	tem (SSTS) to be pumpe	ed through the maintenance hole	, have
L	(OWNer's name) refuse	to allowah		
hole. I understand that removal of solids			olids and liquids through the maint	enance
4. Is the tank designed as a leaky tank? exam	ople: seepage pit, cesspool	drwell leaching nit	sidered maintenance.	
Tank#1 Yes No Verificatio Metl		and the second of the second o		
· /				
Tank#2 Yes No Verificatio Meth	od Used: ————————————————————————————————————			•
is there evidence of tank leakage from a damaged, cracked, or structurally unsou	septic, holding, pretre	atment or pump tank be	elow the operating depth or evide	ance of
Tank	Leaking Out	Leaking In	1	1100 01
Septic/Holding Tank #1	Yes No		Cover Damage	
Septic/Holding Tank #2	Yes No	Yes No	Yes No	
Pretreatment Tank	☐Yes ☐No	Yes No	Yes No	
Pump Tank	☐Yes ☐No	Yes No	Yes No	
6. How many gallons of septage were remove	/ed?	Lies Lino	☐ Yes ☐ No	
Tank#1 /) 50 Tank#2 /) 5	7 1			
12	Pretreatment Ta		mp Tank	
7. Other information: List any troubleshooting	ng, minor repairs condu	cted, tank safety conce	rns, or other concerns.	
8. Certification: Thereby and for the second				
8. Certification: I hereby certify as a State of M and made the observations, o	innesota certified SSTS N	laintainer that I personali	y conducted the work	
Maintainer's Name: Olson's Sewer Service, In		s Address: 17638 Lyons S		
Maintainer's License #: 216 Maintain	ner's Phone #: 651-464-		, O'EST Lake, MN	_
Maintainer's Signature		Date: 7~	/2-23	
9 19/10				