

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be complete					
prior to perfor	ming maintenance activiti	es and remain on-	site for the durati	on of the maintenance	e activity.
Date of Maintenance:	7-27-16 Reason	for Maintenance:	Soution	1000	enanc
Property Address:	570 Northbrook	(BlydN P	roperty Owner's Na	ame:Sharor	Daul
Municipality;	water zip550	Property Iden	tification Number:		_
	: 17/42 e 3294 M				3
maintenance i emili ite	11100 630111				
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum m	easured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to b		evel X 100	e e		
☐ Yes ☐ No (if no provide measurements) = % Sludge & Scum Tanks must be pu					f 25% or greater
1. Access used to rem	nove septage: A Maintena	nce Hole 🗌 Other (e	nter authorization co	ode)	
2. Were all covers securely replaced? 🔎 Yes 🗆 No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ¶ No	☐ Yes ♣TNo	☐ Yes A No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes A No	☐ Yes ☐No	☐ Yes HNo	
4. How many gallons	of septage were removed	?			
Tank #1 1250	gal Tank #2	gal Pretreatmen	t tankg	al Pump Tank	gal
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
	- 11 				
,	e.				
6. Location of septage	WE SEE THE SEE				