

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed						
<u>prior</u> to perfor	ming maintenance activit	ies and remain <u>on</u>	site for the duration	on of the maintena	nce activity.	
Date of Maintenance:	8-15-16 Reason	for Maintenance:	Zoutin	e Maint	Tenance	
Property Address: 2	165 Mannino	Aven 1	roperty Owner's Na	ame: Davic	Hipes	
4	Elmo ZIP550	,			•	
		. •			103	
Maintenance Permit N	<u>::[498]3282 1</u>	vaintainer Name ar	id License No. Ron's	s sewer service/ Lz	103	
Maintenance Performed		Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum _	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if	no provide measurements)	= % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers securely replaced? Yes \(\subseteq \) No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ♣ No	☐ Yes █ No	☐ Yes ☐No	·	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	· •	
4. How many gallons	of septage were removed	i?				
Tank #1 /250 gal Tank #2		_gal Pretreatmen	t tankga	al Pump Tank	gal	
	: List any troubleshooting				er concerns.	
						
6. Location of septage	e disposal:					

Maintenance activities must be reported to the Department within 90 days.