

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be o	completed in its entirety i	to constitute a val	id maintenance pe	ermit. This permit m	ust be completed
<u>prior</u> to perforr	ning maintenançe activiti	es and remain on-	site for the durati	on of the maintenan	ce activity.
Date of Maintenance:	7-5-16 Reason	for Maintenance:	Kes Me	adiat	
Property Address: 22	495 Olinda -	1 (1)		ame: Joanne	Selchert
Municipality: Scal	21. CA ZIP:550	77Property Ider	ntification Number:		
	1001 2/20				429
Maintenance Permit No	31376E2020 N	Maintainer Name ar	d License No. Sim	lie's Sewer Service/L2	.420
/ Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
	ove septage: Maintenar		enter authorization co	ode)	
	urely replaced? 🖊 Yes [8 J. 100	
	f tank leakage from a sep ged, cracked, or structura				ating depth or
•	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes 🗖 No	☐ Yes ☑No	☐ Yes No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 / 00 C	gal Tank #2	gal Pretreatmen	t tankg	al Pump Tank	gal
5. Other information:	List any troubleshooting	– , minor repairs co	nducted, tank safe	ety concerns, or othe	r concerns.
13			, ,	//. /	
6. Location of septage		/	, ,		