## GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 7/31/23	Reason for Maintenance	CIHII	631300	
Property Address: 19411 Force	st Blud	Property Owner's Name	Hex Nigo	
Municipality: Forest Lake	State MN Z	ip Code 65025	- NICX IVIDA	
La William Control		NAME OF TAXABLE PARTY.		
Tank(s) Pumped			ba omilie Heribijajaj	
Sludge and scum measured.	Liquid Level	of Taffik in. Sli	udge Level in. Scum Le	
Do tanks need to be pumped?	7		- Scampe	vel in.
Yes No (If no provide measu	rements) Total (Sludge		id Level = %Sludge &	Scum
1. Access used to remove septage:	faintenance Hole 📋 O	ther (Go to #3 below)	* Tank must be many	
2. If maintenance hole was used, were all	covers securely replaced	? Xi Ves Tible Plans	is greater than 25%.	a ii tuis value
explanation:				
3. If owner refuses to allow a Subsurface them complete and sign the following	Sewage Treatment Cu	there (PARAL )		
them complete and sign the following	statement:	stem (2212) to be brimbi	ed through the maintenance f	ole, have
<b>L</b>	(owner's name), refuse	to allow the remains		
hole. I understand that removal of solids  4. Is the tank designed as a leaky tank?	and liquids through other	et access points is not on a	olids and liquids through the m	aintenance
4. is the tank designed as a leaky tank? exam	npie: seepage pit, cesspoo	l. drwell. leaching nit	sidered maintenance.	
Tank#1 Yes No Verificatio Met		, my conficulting pit		
Tout the fifth . Am	4			E
This remiratio Meth	hod Used:			
5. Is there evidence of tank leakage from a damaged, cracked, or structurally unsou	septic, holding, pretre	atment or pump tank be	elow the operating depth or or	viden if
Tank	Leaking Out	1	r.	Argente of
Septic/Holding Tank #1	Yes No	Leaking In	Cover Damage	,
Septic/Holding Tank #2	Yes No	Yes DNo	Yes DNo	
Pretreatment Tank	☐Yes ☐No	Yes No	Yes No	Vg.
Pump Tank	☐Yes ☑No	Yes No	Yes No	
6. How many gallons of septage were remove	red?	Yes No	Yes No	
Tank#1 1200 Tank#2 100	_	-•		
		Pu:	mp Tank 400	
7. Other information: List any troubleshooti	ng, minor repairs condu	icted, tank safety concer	ns, or other concerns.	
8. Certification: I hereby certify as a State of M and made the observations, or	imnesota certified SSTS North and Control of the co	laintainer that I personally	conducted the work	
Maintainer's Name: Olson's Sewer Service, In		,		
Maine		s Address: 17638 Lyons S	treet NE, Forest Lake, MN	
	ner's Phone #: 651-464-	2082	ý.	
Maintainer's Signature	11	Date: 7/	31/23	
,		7	7	