

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be o	completed in its entirety	to constitute a va	lid maintenance p	ermit. This permit	must be completed
	ning maintenance activit				
Date of Maintenance: (T_{-} Γ	for Maintenance:	Λ	last	
∇	778 N 1	1 1			1
Property Address:	10 //annino	TheN	Property Owner's N	ame: Srey	ans oc
Municipality: 57	Water ZIP:3500	Property Ide	ntification Number		
Maintenance Permit No	0007 (77	— Naintainer Name a	nd License No. Smi	lie's Sewer Service/L	2428
		named Hame a	The License No	tie 3 Jewer Jervice/L	.2420
/ Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if n	o provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remo	ove septage: Maintenar	nce Hole 🗌 Other (enter authorization co	ode)	
	urely replaced? Yes [
	tank leakage from a sep		reatment or nump	tank below the ope	rating depth or
evidence of damag	ed, cracked, or structura	ally unsound main	tenance hole cove	rs?	ating acptin of
-	Tank	Leaking Out	Leaking In	Cover Damage	
-	Septic/Holding Tank #1	☐ Yes 🗗 No	☐ Yes ☐No	☐ Yes ☐ No	
:	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4 How many gallons o	f septage were removed?				
10-101			t tank g	al Ruma Tank	gal
	gal Tank #2 List any troubleshooting,				gal
5. Other information.	cist any troubleshooting,	illillor repairs co	nducted, talik sale	ty concerns, or othe	er concerns.
		1	7.5%		
6. Location of septage	disposal: 1/05	60	/ wad i	Analys	3
	1000		Lucy /	11/1/	
					V