

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety		59	127-7	-
<u>prior</u> to perfor	ming maintenance activiti	es and remain on	-site for the durati	on of the maintena	nce activity.
Date of Maintenance:	8/0/16 Reason	for Maintenance:	Koulson	2	
Property Address:	931 Oboslak	e TIN	Property Owner's Na	amo: Sies /c	ostoch
Municipality:	Vilmo IIP:	Property Ide	ntification Number:		-2428
Maintenance Permit N	0: j.S.255C3/19N	aintainer Name a	nd License No.	The Sou	er Sarvia
Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers see3. Is there evidence of	nove septage: Maintenar curely replaced? Yes of of tank leakage from a sep nged, cracked, or structura	□ No tic, holding, preti	eatment or pump (ank below the ope	rating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes No	☐ Yes ♠No	☐ Yes No	•
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?				
Tank #1 /500 gal Tank #2		gal Pretreatmen	t tankga	l Pump Tank	gal
5. Other information	List any troubleshooting,	minor repairs co	nducted, tank safet	ty concerns, or oth	er concerns.

Maintenance activities must be reported to the Department within 90 days.