

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be o	completed in its entirety to	o constitute a va	id maintenance pe	rmit. This permit mu	st be completed
<u>prior</u> to perforn	ning maintenance activitie	s and remain on	site for the duration	on of the maintenance	e activity.
Date of Maintenance:	7-29-/6 Reason f	or Maintenance: _	Cleaning		
Property Address: 20	949 Meadow 6000	K Ave F	roperty Owner's Na	me: Lauric	otte
Municipality: $5can$	lia ZIP: 550	7.3 Property Ider	ntification Number:		_
Maintenance Permit No	:9070193369 Ma	aintainer Name ar	d License No. Smili	e's Sewer Service/L24	28
Maintenan	ce Performed	Tank Meas	urement (must be	completed if tanks NC	T pumped)
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be	e pumped?	Sludge + Scum / Liquid Level X 100			
$lackiigsquigarrow$ Yes \Box No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers sect Is there evidence of 	ove septage: Maintenand urely replaced? Yes tank leakage from a sept ged, cracked, or structural	No ic, holding, pretr	eatment or pump t	ank below the operat	ing depth or
_	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ੴNo	☐ Yes ☐No	☐ Yes ☑No	
	Septic/Holding Tank #2	☐ Yes ੴNo	☐ Yes ☐No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
_	Pump Tank	☐ Yes ☑No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of	f septage were removed?				
Tank #1 1 a 0a				1000 CO. C.	
Tallk #1 1000		gal Pretreatment	tankga	l Pump Tank 300	gal
	gal Tank #2 1000 List any troubleshooting,				