

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety t	o constitute a v	alid maintenance	permit. This permit	must be completed
<u>prior</u> to performing maintenance activitie	es and remain o	n-site for the dura	tion of the maintena	nce activity.
Date of Maintenance: 8/2/16 Reason f	or Maintenance:	Rostine		
Property Address: 14355- 200 mls)	Property Owner's	Name: Jeny K	echnowie
Municipality: Marine on SF ZIP:	Property Ide	entification Numbe	r:	2.60
Maintenance Permit No: 10563003616Ma	aintainer Name a	nd License No. S	silses Sewe	- Service
Maintenance Performed	Tank Mea	surement (must be	e completed if tanks	NOT pumped)
Tank(s) Pumped	Liquid Level of Tank in			
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Access used to remove septage: Maintenance Were all covers securely replaced? Yes Is there evidence of tank leakage from a septi evidence of damaged, cracked, or structural 	No c, holding, pret	reatment or pump	tank below the ope	rating depth or
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☒No	☐ Yes No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☑No	☐ Yes ☐No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?				
Tank #1 1000 gal Tank #2 1000 gal Pretreatment tank			al Pump Tank	gal
5. Other information: List any troubleshooting, n	ninor repairs cor	nducted, tank safe	ety concerns, or othe	r concerns.