## GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT

	Reason for Maintenance	7680 ==	3531307	
Property Address: 10020 190	7th st N	Property Owner's Name	David + Terri Cook	
Municipality: Forest Lake				_
e Living with the consideration			EO Code/Property I.D. #:	
Tank(s) Pumped			hasamalagella alsana paraistisk	, in
Sludge and scum measured.  Do tanks need to be pumped?	Liquid Level		dge Level in. Scum Level	i
Yes No (If no provide measur	rements) Total (Sludge		d Level = %Sludge & Scum	
1. Access used to remove septage:	aintenance Hote Cio	har 15- a real a		_
2. If maintenance hole was used, were all o	overs securely replaced	ner (GD to #3 below)  Yes No please	<ul> <li>Tank must be pumped if this was is greater than 25%.</li> </ul>	alu
Explanation:				
3. If owner refuses to allow a Subsurface them complete and sign the following	Sewage Treatment Sys	stem (SSTS) to be pumpe	ed through the maintenance hole how	_
l,				
hole. I understand that removed of colide	(owner's name), refuse	to allow the removal of s	olids and liquids through the maintenant	50
hole. I understand that removal of solids a 4. Is the tank designed as a leaky tank? example of the solids are solids.	and liquids through other	er access points is not con	sidered maintenance.	æ
Tank#1 ☐ Yes █ No Verificatio Meth	nod Used:	l, drywell, leaching pit		
Tank#2 ☐ Yes - No Verificatio Meth		25		
5. Is there evidence the table	od Used: Visuo	4		ine.
<ol><li>Is there evidence of tank leakage from a damaged, cracked, or structurally unsou</li></ol>	septic, holding, pretre	atment or pump tank be	low the operating depth or evidence	
Tank	Leaking Out	F.	i	7
Septic/Holding Tank #1	Yes No	Leaking In	Cover Damage	
Septic/Holding Tank #2	Yes No	Yes Pino	Yes tino	
Pretreatment Tank	Yes No	Yes No	Yes No	
Pump Tank	Yes No	Yes No	☐ Yes ☐ No	
6. How many gallons of septage were remov		Yes No	☐ Yes ☐ No	
1200	Pretreatment Ta		mp Tank	
7. Other information: List any troubleshooting	g, minor repairs condu	icted, tank safety concer	ns, or other concerns.	
B. Certification: Thereby certify as a State of Ma				
B. Certification: I hereby certify as a State of Mi and made the observations, or	innesota certified SSTS No. in directly supervised or his	laintainer that I personally	conducted the work	
Maintainer's Name: Olson's Sewer Service, Inc		's Address: 17638 Lyons S	· -	
Maintainer's License #: 216 Maintain			THE POPEST LAKE, MN	
Maintainer's Signature	ner's Phone #: 651-464-		,	
- 4		Date: 8/1/	123	