GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance	525-73	Reason for	Maintenan	ce:	M_	276	700	<i>- ۱۱ ک</i>
Property Address:	375 S	Conalle	or trail	Property (Owner's N	ame: Tow	10(\$)	3010
Municipality: Folest	LAVE	Sta	ate(MW)	= Zip Code	5×25		/Property I.D. #	Cobi Ve Hill a
Was all the state of	esy		Patrai	Warrens		-		
Pank(s) Pumped	THE PERSON NAMED IN COST OF THE PARTY.						lag tip roeg	Open play
Sludge and scum measured.		-	Liquid Leve	i of Tafik	in.	Sludge Leve	l in. sc	cum Level in
Do tanks need to be pumped? Yes No Uf no provide measuremental			otal (Sludg	O A Counch				
	provide measure	ements)		_		iquid Level	= %510	ıdge & Scum
1. Access used to remove s	eptage: Ma	Intenance	Hole 📋	ther (Go to #	3 below)	#	Tank must be p	oumped if this value
2. If maintenance hole was used, were all covers securely replaced? No please explain is greater than 25%.								25%.
Explanation:				(
3. If owner refuses to allow them complete and sign	a Subsurface !	Sewage Tr	eatment S	vstem (SSTC)	to be now			
tnem complete and sign	the following s	tatement:		, over 11 (2213)	in ne bili	npea throug	the mainten	ance hole, have
<i>l</i>		(owner's n	ame), refu	e to allow the	P removal	of colide and	P	the maintenance
hole. I understand that rer						or solids and ; Considered w	ilquids through	the maintenance
4. Is the tank designed as a le	aky tank? <i>examp</i>	ole: seepage	pit, cesspo	ol, drywell, lea	ching pit		onnenante.	
The state of the s	Verificatio Meth							
Tank#2 Yes No	/erificatio Metho	— ئے ادر دادا اس						
	nakaaa firan -	od Usea:						•
5. Is there evidence of tank le damaged, cracked, or stru	cturally unsoun	ieptic, noj id mainter	ding, preti nance hole	eatment or p covers?	oump tan	below the c	perating dept	h or evidence of
			Leaking Out		Leaking In		Cover Damage	
	Septic/Holding Tank #1		Yes No		☐ Yes ☐ No		Yes No	
Septic/Holding Tank #2		☐ Yes	No	1	No			
Pretreatment Tank		Yes	No	7	□No		es □No	_
Pump Tank		Yes	□No		□No		es [No	_
6. How many gallons of septag	je were remove	ed?						-
Tank#1 O Tank#2 Pretreatment Tank Pump Tank								
7. Other information: List any (roubleshooting	g, minor re	epairs conc	lucted tank		and tell		
			,	mered fally:	ealety COI	icerns, or oth	er concerns.	
3. Certification: I hereby certify and made the c	as a State of Mir	nesota ce	tified SSTS	Maintaine: th	at I norre	andt.		
			pervised ot	ners in the pe	formance	rally conduction of this job.	ed the work	
Maintainer's Name: Olson's Se	wer Service, Inc.	•			•		orest Lake, MN	
Maintainer's License #: 216	Maintain	r's Phone	651-46				OTEST LAKE, MIN	
-	SNIL	A	00 1-464	F2U8Z		8.10	13	
Maintainer's Signature	010				Date:	000	" W	
		0			-		-	