

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a val	id maintenance pe	ermit. This permit n	nust be complete	
<u>prior</u> to perfor	ming maintenance activit	ies and remain on-	site for the durati	on of the maintenar	ice activity.	
Date of Maintenance:	8/32/16 Reason	for Maintenance: _	Rostine			
Property Address: 120	890 Hano A	be N P	roperty Owner's Na	ame: Sem	Instal	
Municipality: <u>W./</u>			ntification Number:			
Maintenance Permit No	0:232493946 N	Maintainer Name ar	d License No. Smil	lie's Sewer Service/L	2428	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
\square Yes \square No (if no provide measurements)		= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	ove septage: Maintena	nce Hole 🗌 Other (e	enter authorization co	ode)		
2. Were all covers sec	curely replaced? XYes	□No				
	f tank leakage from a sep ged, cracked, or structur				ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes 🗘 No	☐ Yes 🕅 No	☐ Yes ☐No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	?				
Tank #1 /350	gal Tank #2	gal Pretreatmen	t tankg	al Pump Tank	gal	
	List any troubleshooting				er concerns.	
6. Location of septage	disposal:					