## GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT

Date of Maintenance 8/88/23	Reason for Maintenance	+838	783200
Property Address: 10604. 230-	th St	Property Owner's Name	
Municipality: Role Scandia			ED Code/Property I.D. #:
La Vinter on Comeny (in		- 4000	la omilação de maio em estado e
Tank(s) Pumped			
Sludge and scum measured.  Do tanks need to be pumped?	Liquid Level	of Taffk in. Slu	in. Scum Level in
Yes No (If no provide measur	rements) Total (Sludge	+ Scum) / Liqui	id Level = %Sludge & Scum
1. Access used to remove septage:	aintenance Hole MO	her (Go to #2 holous)	
2. If maintenance hole was used, were all c	overs securely replaced	Yes No please	* Tank must be pumped if this value is greater than 25%. explain
Explanation:			
3. If owner refuses to allow a Subsurface them complete and sign the following	Sewage Treatment Sys statement:	tem (SSTS) to be pumpe	ed through the maintenance hole, have
<b>L</b>			
hole. I understand that removal of solids:  4. Is the tank designed as a leaky tank?	and liquids through other	to allow the removal of s	olids and liquids through the maintenance
4. Is the tank designed as a leaky tank? exam	ple: seepage pit, cesspool	drivell leaching nie	sidered maintenance.
Tank#1 Yes No Verificatio Meth	nod Used:	w l	
Tank#2 Yes No Verificatio Meth		(	
5. is there evidence of tank leakage from a damaged, cracked, or structurally unsou	const. 6 - 6.44		flow the operating death as a side
Tank	1		a septiment evidence of
Septic/Holding Tank#1	Leaking Out  Yes 100	Leaking In	Cover Damage
Septic/Holding Tank #2	Yes Ato	Yes two	Yes Atto
Pretreatment Tank	☐Yes ☐No	Yes No	Yes No
Pump Tank	Yes No	Yes No	☐Yes ☐No
6. How many gallons of septage were remov	ents	Yes No	Li Yes Al No
Tank#1 1000 Tank#2 1000		nt	
7. Other information: List any troubleshooting			mp Tank 380
<u> </u>	ar miler repairs condu	cted, tank safety concer	ns, or other concerns.
8. Certification: I hereby certify as a State of Mi	Phototo and P. J. Comp. L.		
8. Certification: I hereby certify as a State of Mi and made the observations, or	directly supervised other	aintainer that I personally	conducted the work
Maintainer's Name: Olson's Sewer Service, Inc		s Address: 17638 Lyons S	-
Maintainer's License #: 216 Maintain	er's Phone #: 651-464-		TOTES LAKE, MN
Maintainer's Signature	A	Date: 4/	back
		-vic. 4/	7 (27)