

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT **GOVERNMENT CENTER**

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety to				
<u>prior</u> to perfor	ning maintenance activitie	es and remain on-	site for the duration	on of the maintenance	e activity.
Date of Maintenance:	8/18/16 Reason fo	or Maintenance:	Rou pine		
Property Address: //	14 Mekoslet	CON P	roperty Owner's Na	me: les kates	1 Mond
Municipality: 54///		<del></del>	tification Number:		_
Maintenance Permit No	0:035/4c3746 Ma	aintainer Name an	d License No. Smil	ie's Sewer Service/L24	128
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	nove septage: Maintenan	ce Hole 🗌 Other (e	nter authorization co	de)	
2. Were all covers see	curely replaced? X Yes	□No			
3. Is there evidence of	of tank leakage from a sept ged, cracked, or structura	ic, holding, pretr	eatment or pump tenance hole cove	tank below the opera rs?	ting depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes No	☐ Yes KNo	☐ Yes →No	
	Septic/Holding Tank #2	☐ Yes 🕅 No	☐ Yes ☑No	☐ Yes ☐No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐No	☐ Yes ☐ No	☐ Yes ♠No	
	of septage were removed?				
Tank #1 /200	gal Tank #2 1000	gal Pretreatmen	t tankg	al Pump Tank <u></u>	<b>5</b> gal
5. Other information	: List any troubleshooting,	minor repairs co	nducted, tank safe	ty concerns, or other	concerns.
		<u></u>			
6. Location of septage	e disposal:				