

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety t		1.00	(A)	
<u>prior</u> to perfor	ming maintenance activiti	es and remain on	-site for the durati	on of the maintenand	ce activity.
Date of Maintenance: _	8-16-16 Reason	for Maintenance: _	Cleaning		
Property Address: <u>10</u>	060 Indigo Tr	F	roperty Owner's Na	ame: Beth 1	Vielsen
	t zip: 5511				
Maintenance Permit No	:18648 Z 3700 M	aintainer Name ar	nd License No. Smil	ie's Sewer Service/L2	428
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
✓ Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers sec Is there evidence of 	ove septage: Maintenan curely replaced? Yes [f tank leakage from a sept ged, cracked, or structura	□ No tic, holding, pretr	eatment or pump	tank below the opera	iting depth or
8	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ੴNo	☐ Yes ☐No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?				
Tank #1 1,500	gal Tank #2), 🚳 🕖	gal Pretreatmen	t tankga	al Pump Tank 304	gal gal
5. Other information:	List any troubleshooting,	minor repairs co	nducted, tank safe	ty concerns, or other	concerns.
6. Location of septage	disposal:				