

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	id maintenance p	ermit. This permit m	oust be completed	
prior to perfor	ming maintenance activit	ies and remain on	site for the durat	ion of the maintenan	ce activity.	
Date of Maintenance:	7-12-16 Reason	for Maintenance:	Kea M			
10	Winn A	1 1/		7) (()	Dil	
Property Address: 19	9// Oxboro	Hue /V F	roperty Owner's N	ame: Lebbie	retesson	
Municipality: Mar	Sio ZIP: 550	Property Ider	ntification Number:			
1 10.1	VIIIA 7777					
Maintenance Permit No	0: VO 770m) () C	Maintainer Name ar	d License No. Smi	lie's Sewer Service/L	2428	
/ Maintenar	nce Performed	Tank Meas	urement (must be	completed if tanks h	NOT pumped)	
Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
	no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
	1 2					
1. Access used to rem	nove septage: 🗐 Majntena	nce Hole $\Box$ Other (e	enter authorization co	ode)		
2. Were all covers see	curely replaced?  \( \square\) Yes	□No				
3. Is there evidence of	of tank leakage from a sep ged, cracked, or structur	otic, holding, pretr			ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes 🖒 No	☐ Yes ♠No		
	Septic/Holding Tank #2	☐ Yes 🗹 Mo	☐ Yes ☑ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	$\square$ Yes $\square$ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	  ?				
1 1	gal Tank #2 1750	-	tank g	al Pump Tank	gal	
	: List any troubleshooting					
5. Other information	. List any troubleshooting	,, millor repairs co.	radeced, came sare	,		
***************************************						
		_				
6. Location of septage	disposal: Mac		101	Angli		