

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	lid maintenance po	ermit. This permit mu	ust be completed
<u>prior</u> to perfor	ming maintenance activit	ies and remain on	site for the durati	on of the maintenance	e activity.
Date of Maintenance:	Reason	for Maintenance:	Keg M	Acta)	
Property Address: //	120 12151	-571/	Property Owner's N	ame: Chnis	Hause
Municipality:	Jun Pr ZIP: 53	500	ntification Number:		, , , , , , , , , , , , , , , , , , ,
	10751 12-70				
Maintenance Permit No	: <u>a10)18527</u> 1	Maintainer Name ar	nd License No. Smi	lie's Sewer Service/L24	428
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers sec Is there evidence of 	ove septage: Maintenar curely replaced? Yes [f tank leakage from a sep ged, cracked, or structura	□ No tic, holding, pretr	eatment or pump	tank below the opera	ting depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
,	Septic/Holding Tank #1	☐ Yes No	☐ Yes ☐ No	☐ Yes ⊅No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?	4		
Tank #1 100	gal Tank #2	gal Pretreatmen	t tankg	al Pump Tank	gal
5. Other information:	List any troubleshooting,	minor repairs co	nducted, tank safe	ty concerns, or other	concerns.
-	1.101		1	1 / /	/
6. Location of septage	disposal: M/US/	1 (0	Luco	//DPh	