Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #:	
Property Address: 18070 July Ave N Forestlake MN 55025 Street Address City State Zip Property Owner Name: Paul Schmid	
Maintenance Performed Tanks Pumped: □ Emergency □ Home Sale □ High-level alarm ✓ Routine/Maintenance □ Compliance Inspection □ Repair □ Other: Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scum Tanks must be Pumped if 25% or greater	
Maintenance Information Were all covers securely replaced? Yes No If No, Explain: Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit Tank #1: Yes No Verification Method Used Gallons Removed: Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Tank #3: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Pump Tank: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Pump Tank: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Waste Disposal Method: Treatment plant Land Apply: Location A) 105 89 03 Other remarks or Concerns: All Apply: Location	
Maintainer Information Maintainer Name: Sherco Construction, Inc. Maintainer Address: 79 North Lake Street Forest Lake MN 55025	

Phone Number: (651) 462-1817 License Number: L1675

I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.

Maintenance activities must be reported to the Department within 90 days.

