

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

	rforming maintenance activit					
	ce: <u>9523</u> Reason					
Property Address:_	9363 190T	rly b	roperty Owner's Na	ame: Sharon	Leehan	
Municipality: Sor	est Lake ZIP: 550	25 Property Idea	ntification Number:	11		
Maintenance Permi				Sewer Service - L330	9	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need	to be pumped?	Sludge + Scum -	Sludge + Scum / Liquid Level X 100			
Yes No	(if no provide measurements)	= % Sludge & Sci	ım Ta	an <u>ks must be pumpe</u>	cif 25% or greater	
		Leaking Out Yes No	Leaking In  Yes No  Yes No	Cover Damage YesNo	9-15-2022	
	St		Yes No		od it 3	
	Pump Tank	Yes No	Yes No	Yes No	LVKA	
Tank #1 1000	s of septage were removed?gal Tank #2 n: List any troubleshooting, i	gal Pretreatment	tankga	l Pump Tank	gal er concerns.	
6. Location of septag	e disposal: A) Rell	eir field	15 01.0	0089.00		
	P: 651-4	Row Sewer Ser O. Box 236 - 412 E Taylors Falls, MN	Bench St.	RECE	<b>EIVED</b> 1 5 2023	
N)	1.031-4	op Jour FICGUSE	Number: L3309	100000000000000000000000000000000000000	a second I	

Maintenance activities must be reported to the Department within 190 days. HEALIH

White Copy-Maintainer submits to Washington County/Yellow Copy-Maintainer Record/Pink Copy-Property Owner Record