

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety prior to performing maintenance activi	ties and remain on-	site for the durati			
Date of Maintenance: 6-9-23 Reason	n for Maintenance: _	Thorsine			
Troperty Madressi		roperty Owner's Na		chenny	
Municipality: <u>Clue 1-1/wa</u> ZIP: <u>55</u>	Property Ider	tification Number:			
Maintenance Permit No: <u>+305/03/063</u>	Maintainer Name an	d License No. <u>Pink</u> y	's Sewer Service Inco	orporated/ L4251	
Maintenance Performed	Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped	Liquid Level of 1	Liquid Level of Tank — in			
☐ Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum	Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements	s) = % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage:   Mainten	ance Hole Other (e	nter authorization co	ode)		
2. Were all covers securely replaced? $\hfill \square$ Yes	□ No				
<ol><li>Is there evidence of tank leakage from a se evidence of damaged, cracked, or structu</li></ol>				ating depth or	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	Yes □ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were remove  Tank #1 / Occopy gal Tank #2 / Occopy		tankg	al Pump Tank	gal	
5. Other information: List any troubleshootin  Our  6. Location of septage disposal:	g, minor repairs con	nducted, tank safe	ty concerns, or othe		

Pinky's Sewer Service Incorporated

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L4251