## GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT

Date of Maintenance 6-2-2	Reason for Maintena	ince: Wasana	,	
Property Address: 10		K0418 b	32778	
1933	Merely Ridge	Property Owner's Na	me: Dr	
Property Address: 1933	State	Zip Code	The bale	
Ve. o ( ) (eng)			Code/Property I.D. F.	
☑ Fank(s) Pumped			Crequility Hanthogs	
Sludge and soum measured	Liquid Lev	1 -1 - A		
tanks need to be pumped?	1		Scum Le	vet in.
2 (ii no provide med	surements) Total (Slud		uid Level = %Sludge &	Scum
7. Access used to remove septage:	Maintenance Hole Til	Other (Goto #3 Later)		- 1
2. If maintenance hole was used, were all Explanation.	Covers securely rentace	d? Ass Delow)	<ul> <li>Tank must be pumped is greater than 25%.</li> </ul>	if this value
Explanation:	tepiste in the property of the	Yes No pleas	explain	
3. If owner refuses to allow a Subsurfacthem complete and sign the following	e Sewage Treatment S	ystem (SSTS) to be pump	sed through at	
l, ·	g statement:		through the mainlenance he	ole, have
hole. I understand that removed of called	(owner's name), refus	e to allow the removal of	solids and liquids through the mai	
hole. I understand that removal of solid.  6. Is the tank designed as a leaky tank? example of the solid.	s and liquids through oth	ner access points is not co	nsidered maintenance	intenance (
- ·	and	ol, drywell, leaching pit		•
Z vernicatio met	d -			
Tank#2 Yes WNo Verificatio Met	hod Used:		9	
5. Is there evidence of tank leakage from a damaged, cracked, or structurally unsor	septic, holding, pretra	elment or numer to all the		
Tonk	ind maintenance hole o	overs?	elow the operating depth or evid	Sence of
Tank Septic/Holding Tank#1	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank#2	☐Yes ☐No	Yes No	Yes Who	
Pretreatment Tank	Yes No	Yes No	Yes Kino	
Pump Tank	☐Yes ☐No ☐Yes ☐No	Yes No	☐Yes ☐No	
6. How many galions of septage were remove	Lifes Lino	☐ Yes ☐ No ☐	[]Yes []No	
Tankers				
7. Other inc.	Pretreatment Tar	nkPur	np Tank	
7. Other information: List any troubleshootin	g, minor repairs condu	cted, tank safety concer	DS. Orothoron	
B. Certification: I bond			or other concerns,	
B. Certification: I hereby certify as a State of Mi and made the observations, or Maintainer's Names Of the Control of the Con	nnesota certified SSTS Mi directly supervised other	aintainer that I personally	conducted the work	-
Maintainer's Name: Olson's Sewer Service, Inc		Address: 17638 Lyons St		
Maintainer's License #: 216 Maintain	er's Phone #: 651-464-2	082	rees NE, Forest Lake, MN	_
Maintainer's Signature	/			
101	An C	Date: 10-0	1-23	
	0			