GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 10 (a)	Reason for Mainten	ance: ACT O	,	
Property Address: 10080 T	2001	C ath	915 3254	2
Municipality:	the work	Property Owner's Na	me: Selh Steint	pach
vatua o to eny	The state of the s	Zip Code SSUS	GEO Code/Property I.D. E.	
Tenk(s) Pumped		10.000 mie fieling land	() នេះប្រាជ្ញន្ន មានសង្ឃ	
Sludge and scum measured.	Liquid Lev	us sm Ar		
Do tanks need to be pumped?	11	****	Sludge Level in. Scul	mLevet in
Yes No (If no provide meas		ge + Scum) / Liq	uid Level = % (lud	
T. Access used to remove septage:	Maintenance Hole Ti	Others	- 100	ge & Scum
2. If maintenance hole was used, were all	Covers securely reals	Other (Go to #3 below)	* Tank must be put is greater than 25	mped if this value
- de la		(
3. If owner refuses to allow a Subsurfac them complete and sign the following	e Sewage Treatment S	Velom (CCTC)		
. Complete and sign the following	g statement:	1975 ne pump	ed through the maintenan	ce hole, have
, -	(0.000 -)	•		
hole. I understand that removal of solids 6. Is the tank designed as a leaky tank? exar	and liquids through oti	her access points is not co	solids and liquids through the	maintenance
	mple: seepage pit, cesspo	ol, drywell, leaching pit	isidered maintenance.	
Tank#1 Yes No Verificatio Met	hod Used:			
Tank#2 Yes No Verificatio Meti	hod Head			
5. Is there evidence of tank leakage from a damaged, cracked, or structurally unsou	septic, holding, pretri	ealment or numer court.		TRIT
Tout	ind maintenance hole	covers?	elow the operating depth or	evidence of
Tank Septic/Holding Tank #1	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #2	Yes Ko	Yes INO	[] Yes []No	
Pretreatment Tank	Yes No	Yes No	Yes No	
Pump Tank	Yes No	☐ Yes ☐ No	Yes No	
6. How many gallons of septage were remov	ed?	Yes No	□ Yes □ No	
Tank#1 Tank#2	Pretreatment Ta	nk		
7. Other information: List any troubleshootin	g, minor repairs condu	rur	mp Tank	
	- Pana solice	ctes, tank salety concer	ns, or other concerns.	
8. Certification: I hereby certify as a State of Minand made the observations, or	nnesota certified SSTS M	laintainer that the area at		
and made the observations, or	directly supervised other	rs in the performance of the	Conducted the work	
Maintainer's Name: Olson's Sewer Service, Inc		s Address: 17638 Lyons St		
Maintainer's License #: 216 Maintain	er's Phone #: 651-464-2		rees NE, Forest Lake, MN	
Maintainer's Signature			^2	
V		Date: 0	072	