

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

			NAME AND ADDRESS OF TAXABLE PARTY.	Name and Address of the Owner, where the Party of the Owner, where the Party of the Owner, where the Owner, which is the Owner, wh	
This section must be	e completed in its entirety	to constitute a va	lid maintenance p	ermit. This permit r	must be completed
	orming maintenance activiti			tion of the maintena	nce activity.
Date of Maintenance:	8.30.23 Reason	for Maintenance:	Kelltine		
Property Address: 🔽	260 16t St	MO F	roperty Owner's N	lame: Scott &	husan
Municipality: <u>(()(0</u>	Fluxo ZIP:550	12 Property Idea	ntification Number	:	
Maintenance Permit N	No:11859 e31988 M	laintainer Name ar	d License No. Pink	xy's Environmental Se	wer Service/ L1673
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rer	move septage: Maintenan	ce Hole Other (e			3
	curely replaced? Yes		nter additionzation co	ode)	
evidence of dama	of tank leakage from a sept aged, cracked, or structura	iic, holding, pretr	eatment or pump	tank below the oper	ating depth or
eridence of dame	— aged, cracked, or structura	ity unsound maint	enance note cove	rs? L Yes L No	
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
How many gallons	of septage were removed?				
Tank #1 /500	gal Tank #2	gal Pretreatment	tankga	al Pump Tank	gal
. Other information:	: List any troubleshooting,	minor repairs con	ducted, tank safe	ty concerns, or other	r concerns.
System to	all for manho	le per ho	necure-		
. Location of septage	e disposal: www				_
	,				
	Pinky's	Environmental Sev	ver Service Inc.		
		PO Box 354			
		Afton MN 550	001		

Maintenance activities must be reported to the Department within 90 days.

P: 651-439-4847 License Number: L1673