

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

|   | ty to constitute a valid maintenance permit. This permit must be comple   | ete |
|---|---|-----|
| Date of Maintenance: $8-29-23$ Reason                   | on for Maintenance: Pautiul   |     |
|   | Mo Property Owner's Name: Gary Palwaye  | V   |
| Municipality: ZIP:                                      | Property Identification Number:   |     |
|   | Maintainer Name and License No. <u>Pinky's Environmental Sewer Service/</u> L1  | 67  |
|   |   | 07  |
| Maintenance Performed                                   | Tank Measurement (must be completed if tanks NOT pumped)  |     |
| Tank(s) Pumped  | Liquid Level of Tank — in   |     |
| ☐ Sludge and scum measured                              | Sludge Level in Tank in Scum Level in Tank in   |     |
| Do tanks need to be pumped?                             | Sludge + Scum / Liquid Level X 100  |     |
| $\square$ Yes $\square$ No (if no provide measurements) | s) = % Sludge & Scum Tanks must be pumped if 25% or greate  | r   |
| 1. Access used to remove septage:   Maintena            | nance Hole Other (enter authorization code)   |     |
| 2. Were all covers securely replaced? Yes               |   |     |
|   |   |     |
| evidence of damaged, cracked, or structure              | eptic, holding, pretreatment or pump tank below the operating depth or urally unsound maintenance hole covers?   Yes No |     |
|   |   |     |
| Tank<br>————————————————————————————————————            | Leaking Out Leaking In Cover Damage   |     |
| Septic/Holding Tank #1                                  | ☐ Yes ☐ No ☐ Yes ☐ No   |     |
| Septic/Holding Tank #2                                  | ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No  |     |
| Pretreatment Tank                                       | ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No  |     |
| Pump Tank   | ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No  |     |
| 4. How many gallons of septage were removed?            | d?  |     |
| Tank #1 1250 gal Tank #2                                | gal Pretreatment tankgal Pump Tankgal   |     |
| 5. Other information: List any troubleshooting,         | g, minor repairs conducted, tank safety concerns, or other concerns.  |     |
|   | ing   |     |
|   |   |     |
| 5. Location of septage disposal:www.tr                  | reatment Plint St. Pan  |     |
| Pinky':   | y's Environmental Sewer Service Inc.  |     |
|   | PO Box 354  |     |
|   | Afton MN 55001  |     |

Maintenance activities must be reported to the Department within 90 days.

P: 651-439-4847 License Number: L1673