

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

prior to performing maintenance activiti			rmit. This permit mu	
	for Maintenance: <u>Y</u>			3
			M Source	1 -10-
Property Address: 1625 Oleve Pr	VC NO PI	roperty Owner's Na	me: Michael	Lynsku
	& Property Iden			_
Maintenance Permit No: <u>eの425d31337</u> N	aintainer Name an	d License No. Pinky	r's Environmental Sew	er Service/ L1673
	1			
Maintenance Performed	Tank Measi	rement (must be	completed if tanks N	OT pumped)
✓ Tank(s) Pumped	Liquid Level of Tank ———— in			
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: Maintenar	nce Hole Other (e	nter authorization co	de) TODDI	_
2. Were all covers securely replaced? Yes				
3. Is there evidence of tank leakage from a sep		eatment or pump	tank below the opera	ting depth or
evidence of damaged, cracked, or structura				3 - 1
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank Pump Tank	☐ Yes ☐ No☐ Yes ☐ No☐	☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No	
	☐ Yes ☐ No	_	_	
Pump Tank	☐ Yes ☐ No	Yes No	☐ Yes ☐ No	gal
Pump Tank 4. How many gallons of septage were removed?	Yes No	Yes No	Yes Noal Pump Tank	
Pump Tank 4. How many gallons of septage were removed? Tank #1 1400 gal Tank #2	Yes No	Yes No	Yes Noal Pump Tank	

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673