## Washington County

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

	be completed in its entirety	to constitute a va	lid maintenance p	permit. This permit n	nust be completed	
<u>prior</u> to peri	forming maintenance activi	ties and remain on	-site for the dura	tion of the maintenar	nce activity.	
	e: <u>9-19-23</u> Reason					
Property Address: \(\(\)	5441 Penfreid	Are No	Property Owner's N	Name: Carlene	Heugel	
Municipality: Sh	Munter ZIP: 550	SZ Property Ide	ntification Number	:		
Maintenance Permit	No: <u>13906 x37066</u>	Maintainer Name ar	nd License No. Pink	(V's Environmental Sev	wer Service / 11473	
				y s Environmental Sev	wei service/ L16/3	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank — in			
$\square$ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum				
$\square$ Yes $\square$ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater				
evidence of dam	of tank leakage from a sep naged, cracked, or structure Tank	Leaking Out	enance hole cove	rs?	acing depth of	
	Septic/Holding Tank #1	No. Ou	☐ Yes ☑ No			
		Yes No	L res No	Yes No		
	Septic/Holding Tank #2	☐ Yes ☐ No	Yes No	Yes No		
		_				
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No		
I. How many gallons	Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  of septage were removed?	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No		
Tank #1 15 0	Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  of septage were removed?  gal Tank #2	Yes No Yes No Yes No gal Pretreatment	Yes No Yes No Yes No Yes No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	gal	
Tank #1 15 0	Septic/Holding Tank #2  Pretreatment Tank  Pump Tank	Yes No Yes No Yes No gal Pretreatment	Yes No Yes No Yes No Yes No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	gal concerns.	
Tank #1 15 0	Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  of septage were removed?  gal Tank #2	Yes No Yes No Yes No gal Pretreatment	Yes No Yes No Yes No Yes No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	gal concerns.	
Tank #1 15 D	Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  of septage were removed?  gal Tank #2	Yes No Yes No Yes No gal Pretreatment	Yes No Yes No Yes No Yes No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	gal concerns.	
Tank #1 15 D	Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  of septage were removed?  gal Tank #2  a: List any troubleshooting,  de disposal:	Yes No Yes No Yes No gal Pretreatment minor repairs con	Yes No Yes No Yes No Yes No tank gaducted, tank safet	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	gal concerns.	
Tank #1 15 D	Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  of septage were removed?  gal Tank #2  a: List any troubleshooting,  de disposal:	Yes No Yes No Yes No gal Pretreatment	Yes No Yes No Yes No Yes No tank gaducted, tank safet	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	gal concerns.	

Afton MN 55001

P: 651-439-4847 License Number: L1673