

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

			Description of the second
This section must be completed in its entirety	to constitute a valid maintena	ance permit. This permit n	nust be completed
<u>prior</u> to performing maintenance activit	ies and remain on-site for the	duration of the maintenan	iust be completed
			ice activity.
	for Maintenance:	ine	
Property Address: 16785 Square	Cercom Property Own	ner's Name: Bob M	ichelle
Municipality: Stillwater ZIP: 55	82 Property Identification N	umber:	Fmerso
Maintenance Permit No: £354544 32248 N	Maintainer Name and License No	o. <u>Pinky's Environmental Sev</u>	ver Service/ L1673
Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)		
Tank(s) Pumped	Liquid Level of Tank —		to i pumped)
Sludge and scum measured	Sludge Level in Tank		
Do tanks need to be pumped?	Studen Same		
☐ Yes ☐ No (if no provide measurements)	= % Sludge & Scum		6.25%
	ce Hole Other (enter authorization code)		
 Were all covers securely replaced? Yes Is there evidence of tank leakage from a sept evidence of damaged, cracked, or structura 	tic, holding, pretreatment or p	pump tank below the opera	ating depth or
Tank	Leaking Out Leaking I	n Cover Damage	
Septic/Holding Tank #1	☐ Yes ☐ No ☐ Yes ☐	No ☐ Yes ☐ No	
Septic/Holding Tank #2	☐ Yes ☐ No ☐ Yes ☐	No	
Pretreatment Tank	☐ Yes ☐ No ☐ Yes ☐	No	
Pump Tank	☐ Yes ☐ No ☐ Yes ☐	No Yes No	
4. How many gallons of septage were removed?			
Tank #1 1500 gal Tank #2	gal Pretreatment tank	gal Pump Tank	gal
Other information: List any troubleshooting,	minor repairs conducted, tank	safety concerns or other	gat
nothing		valuely concerns, or other	concerns.
)	
. Location of septage disposal:	atmentplat st.	Rul	
Pinky's	Environmental Sewer Service II	nc.	
	PO Box 354		

Afton MN 55001

P: 651-439-4847 License Number: L1673