GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 10:26-2	3 Reason for Mainten	ance:	13000
Property Address: 2445 P.	eriwink h		JF328885.
Municipality: St. // Weter	State	Zip Code	me: Jastin Hornans
Carlotte of Chemy		Zip Code	GEO Code/Property I.D.e.
Tank(s) Pumped	NG 4 1 2 2 2		(1) (
Do tanks need to be pumped?	Liquid Lev	1474	Słudge Level in. Scum Level in.
Yes No (If no provide meas	Surements) Total (Slud		uid Level = %Sludge&Scum
7. Access used to remove septage:	Maintenance Hole 📋	Other (Go to #3 below)	
2. If maintenance hole was used, were all Explanation.	covers securely replace	d? Kive Fine	is greater than 25%.
		•	
3. If owner refuses to allow a Subsurface them complete and sign the following I, hole. I understand that removal of solids 4. Is the tank designed as a leaky tank? exam Tank#1 Yes No Verificatio Meti Tank#2 Yes No Verificatio Meti 5. Is there evidence of tank leakage from a damaged, cracked, or structurally unsou Tank Septic/Holding Tank #1 Septic/Holding Tank #2	(owner's name), refusional liquids through other processions of the control of th	e to allow the removal of her access points is not co of drywell, leaching pit eatment or pump tank betweens? Leaking In	solids and liquids through the maintenance nsidered maintenance.
Pretreatment Tank	Yes No.	Yes Divo	☐Yes ⋈o
Pump Tank	☐Yes ☐No	☐Yes ☐No	□Yes □No
low many gallons of septage were remove	D'Yes No	☐ Yes KNo	Li Yes Divo
Tank#2 DZZ	Pretropiment To	nk Pui	
Francetion: Thereby certify as a State of the	cruck in	pottom, to	
and made the observations, or intainer's Name: Olson's Sewer Service, Inc.		Transmitting Diffi	15 Job. Chalenan
Indain	er's Phone #: 651-464-2	Address: 17638 Lyons St	reet NE, Forest Leke, MN
Intainer's Signature	'A	·	-26-23