

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	lid maintenance pe	ermit. This permit	must be completed
	rming maintenance activit				
Date of Maintenance:	9-1-23 Reason	for Maintenance:	Zantin		
Property Address:	160 Pinehurst	Rd F	roperty Owner's Na	ame: Branda	n Dahi
Municipality: Pw	Sprmas zip: 551	Property Idea	ntification Number:		
	10: <u>\$276093203</u> 3A				ewer Service/ L1673
	0				
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	nove septage: Maintenar	nce Hole Other (e	nter authorization co	der Too Die	
	ecurely replaced? Yes				
	of tank leakage from a sep		eatment or nump t	ank below the one	rating donth or
evidence of dam	aged, cracked, or structura	ally unsound main	enance hole cover	s? Yes No	rating depth of
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?				
Tank #1 15 00	gal Tank #2	gal Pretreatment	tankga	l Pump Tank	gal
	: List any troubleshooting,				
	nothing				
			0.1		
6. Location of septage	e disposal: ww Tree	tment Pl	at Stylus/		
	Pinky's	s Environmental Se	wer Service Inc.		
		PO Box 35	4		
		Afton MN 55	001		

Maintenance activities must be reported to the Department within 90 days.

P: 651-439-4847 License Number: L1673