GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 11423	Reason for Maintenan	ce: 52181	6C334	21
Property Address: D475	10th Stypall	Property Owner's Nam	e: Vina cla)
Municipality:		- L L L L L L L L L L L L L L L L L L L		The state of the s
William of the sold	CONTROL OF THE PARTY OF THE PAR	WWO.	GEO Code/Property I.D. #	
Tenk(s) Pumped	11	ide tempe in installe	Tromples environ	Oraniyi ji
Do tanks need to be pumped?	Liquid Leve	l of Tafik in. Si	udge Level in. Sc	um Levet in.
Yes No (If no provide measu	rements) Total (Sludg	e + Scum) / Liqu	id Level = %500	dge & Scum
1. Access used to remove septage	31			
2. If maintenance hole was used, were all	covers securely replaced	Yes No please	is greater than a	umped if this value 25%.
Explanation:	/			
If owner refuses to allow a Subsurface them complete and sign the following	Sewage Treatment Sy statement:	stem (SSTS) to be pump	ed through the maintena	ince hole, have
i ,				
hole. I understand that removal of solids 6. Is the tank designed as a leaky tank?	and liquids through oak	e to allow the removal of s	olids and liquids through t	the maintenance
4. Is the tank designed as a leaky tank? exam	iple: seepage nit correct	er access points is not cor	sidered maintenance.	
Tank#1 Yes No Verificatio Met		n, arywell, leaching pit		
Tank#2 Yes No Verificatio Meth	iod Used:			
5. is there evidence of tank leakage from a damaged, cracked, or structurally unsou	septic, holding, pretre	eatment or pump tank be	low the operating depth	Ol evidence il
Tank	Leaking Out	Leaking In	1	- Carnetife Di
Septic/Holding Tank #1	☐Yes ☐No	Yes ONG	Cover Damage	_
Septic/Holding Tank #2	Yes No	Yes ANO	Yes Pino	_
Pretreatment Tank	☐Yes ☐No	Yes No	TYES TNO	-
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	□Yes □No □Yes □No	2
6. How many gallons of septage were remov	ed?		Tites Tino	
Tank#1 235 Tank#2 1000	Pretreatment Ta	nk Pu	mp Tank	
7. Other information: List any troubleshooting	g, minor repairs condu	icted, tank safety concer	ns, or other concerns.	
8. Certification: I hereby certify as a State of Mi	Photosin and P. Learne		_	
8. Certification: I hereby certify as a State of Mi and made the observations, or	directly supervised other	laintainer that I personally ers in the performance of t	conducted the work	
Maintainer's Name: Olson's Sewer Service, Inc		s Address: 17638 Lyons S		
Maintainer's License #: 216 Maintain	ers Phone#: 651-464-		I OIESI LAKE, MN	
Maintainer's Signature		Date:	03	