

520 Lafayette Road North St. Paul, MN 55155-4194

Compliance Inspection Form

Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

requirements and attached for	on Minnesota Pollution Control Agency (MPCA) orms – additional local requirements may also ap Local Unit of Government (LUG) and system	
		<u> </u>
System Status		
	te (mm/dd/yyyy): 9/6/2016	
	26 (IIIII/dd/yyyy). <u>9/0/2010</u>	
	report date, unless shorter time (Se	oncompliant – Notice of Noncompliance be Upgrade Requirements on page 3.)
Reason(s) for none	compliance (check all applicable)	
	(Compliance Component #1) - Imminent threat	to public health and safety
Other Complian	nce Conditions (Compliance Component #3) - In	nminent threat to public health and safety
	Compliance Component #2) – Failing to protect	
	nce Conditions (Compliance Component #3) - F	
	(Compliance Component #4) - Failing to protect	
— U Operating perm	nit/monitoring plan requirements (Compliance Co	отронені #5) — Noncompilani
Property Informatio	n Porosi ID# or So	o/Tum/Pongo: 09 020 20 44 0004
• •	·	c/Twp/Range: 08.030.20.44.0004
Property owner: Howard	Oakgreen Ave N Stillwater, MN 55082	Reason for inspection: Property sale
or	a Jili Starig	Owner's phone:
Owner's representative:	Carmel Carver, Coldwell Banker Burnet Realty	Representative phone: 651-430-7761
	Washington County	Regulatory authority phone: 651-430-6673
Brief system description:	1,250 gallon septic tank & 765 SF of gravity dra	
Comments or recommend		
Tank was pumped on 8-30-	2016.	
Certification		
determination of future syst		ermine the compliance status of this system. No e to unknown conditions during system construction, age.
Inspector name: _Tom Tro	polen	Certification number: 323
Business name: _All State	e Septic Services LLC	License number: 1568
Inspector signature:	Ton Troc	Phone number: 612-594-4496
Nococonni en Lecali	y Doguirod Attachus anta	· · · · · · · · · · · · · · · · · · ·
Soil boring logs		Forms per local ordinance
Other information (list):	

Compi	iance criteria:		Verification method(s):
	discharges sewage to the	☐ Yes ☒ No	☑ Searched for surface outlet
ground	surface.		⊠ Searched for seeping in yard/backup in home
	discharges sewage to drain urface waters.	☐ Yes ☒ No	⊠ Excessive ponding in soil system/D-boxes
	causes sewage backup into	☐ Yes ⊠ No	☐ Homeowner testimony (See Comments/Explanation)
	g or establishment.	□ res ⊠ No	 ☐ "Black soil" above soil dispersal system ☐ System requires "emergency" pumping
Any "	yes" answer above ind	icates the	☐ Performed dye test
system is an imminent threat to public			☐ Unable to verify (See Comments/Explanation)
healti	n and safety.		Other methods not listed (See Comments/Explanation)
Comm	ents/Explanation:		
Tank	Integrity - Compliance	component #2 of 5	
Comp	Compliance criteria:		Verification method(s):
System consists of a seepage pit, cesspool, drywell, or leaching pit.		Yes No	☐ Probed tank(s) bottom
	e pits meeting 7080.2550 may be nt if allowed in local ordinance.		☐ Examined Tank Integrity Form (Attach)
		☐ Yes ⊠ No	Observed liquid level below operating depth
Sewage tank(s) leak below their designed operating depth.			Examined empty (pumped) tanks(s)
If yes,	which sewage tank(s) leaks:		Probed outside tank(s) for "black soil"
	'yes" answer above ind		 ☐ Unable to verify (See Comments/Explanation) ☐ Other methods not listed (See Comments/Explanation)
- outsta	em is failing to protect g	roundwater.	Other methods not have fose commentarizations
			
	ents/Explanation:		
			
			
			
Comm	ents/Explanation:	ns — Compliance com	nnonent #3 of 5
Comm	ents/Explanation: r Compliance Conditio		
Othe	r Compliance Condition aintenance hole covers are dan	naged, cracked, unsecure	ed, or appear to be structurally unsound. 🗌 Yes* 🖾 No 🗍 Unkr
Othe a. M b. O	r Compliance Condition aintenance hole covers are dan	naged, cracked, unsecure	ed, or appear to be structurally unsound. Yes* No Unknersely impact public health or safety.
Othe a. M b. O	r Compliance Condition aintenance hole covers are dan ther issues (electrical hazards, etc.	naged, cracked, unsecure	ed, or appear to be structurally unsound. Yes* No Unknersely impact public health or safety.
Othe a. M b. O	r Compliance Condition aintenance hole covers are dan ther issues (electrical hazards, etc. Bystem is an imminent threat	naged, cracked, unsecure	ed, or appear to be structurally unsound. Yes* No Unknersely impact public health or safety.
Othe a. M b. O	r Compliance Condition aintenance hole covers are dans ther issues (electrical hazards, etc.) System is an imminent threat the explain:	naged, cracked, unsecure .) to immediately and adv to public health and sal	ed, or appear to be structurally unsound. ☐ Yes* ☒ No ☐ Unki rersely impact public health or safety. ☐ Yes* ☒ No ☐ Unki rety.
Othe a. M b. O c. S	r Compliance Condition aintenance hole covers are danther issues (electrical hazards, etc. System is an imminent threat in a system is an imminent threat in a system is an imminent threat in a system is non-protective of grounds.	naged, cracked, unsecure) to immediately and adv to public health and saf	ed, or appear to be structurally unsound. ☐ Yes* ☒ No ☐ Unki
Othe a. M b. O	r Compliance Condition aintenance hole covers are dans ther issues (electrical hazards, etc.) System is an imminent threat the explain:	naged, cracked, unsecure) to immediately and adv to public health and saf	ed, or appear to be structurally unsound. ☐ Yes* ☒ No ☐ Unknersely impact public health or safety. ☐ Yes* ☒ No ☐ Unknersety.

Property address: 10180 Oakgreen Ave N Stillwater, MN 55082

Inspector initials/Date: TT | 9/6/2016

(mm/dd/yyyy)

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31b • 6/4/14 Page 2 of 3

www.pca.state.mnius • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats way-wwists4-31b • 674/14

its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas,

Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

Noett 9616 J House CARAGE SOULD PIPE