GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 11/15/23	Reason for Maintenan	ce: Q 2/	16×335103	
Property Address: 1448 Manni	as Their al	Property Owner's Name		
Municipality: Stillwater			ne: Ray & Sue Hoyt	
A Metivas Concept envis		13082	GEO Code/Property I.D. F:	
Tank(s) Pumped			O Good as elemented and some	
Sludge and scum measured. Do tanks need to be pumped?	Liquid Leve	of Tafik in. Si	ludge Level in. Scum Level	in.
Yes No (If no provide meas	viements) Total (Sludge		nid Level = % Sludge & Scum	1
1. Access used to remove septage:	Maintenance Hole Tio	ther IGo to #3 hatawa	4 Tools	_
2. Il maintenance hole was used, were all	covers securely replaced	? EYes [No please	* Tank must be pumped if this val is greater than 25%. explain	ve
Explanation:				
3. If owner refuses to allow a Subsurface them complete and sign the following	Sewage Treatment Sy	stem (SSTS) to be pump	ed through the maintenance hate	
i, ·				
hole. I understand that removal of solids	(Owner's name), refuse	to allow the removal of s	colids and liquids through the maintenance	
hole. I understand that removal of solids 4. Is the tank designed as a leaky tank? exam	end liquids through other	er access points is not cor	isidered maintenance.	
Tank#1 Tives #This Various to		, arywell, leaching pit		
Tank#1 Yes No Verificatio Met	hod Used: Visual			
1ank#2 Yes No Verificatio Meti	nod liked:			
Is there evidence of tank leakage from a damaged, cracked, or structurally unsou	septic, holding, pretre	elment or numn tank h.	Newsh	
Tank		overs?	now the operating depth or evidence of	
Tank Sentic Westing Task #8	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1 Septic/Holding Tank #2	☐Yes ☐No	Yes - ANO	☐Yes ₺No	
Pretreatment Tank	Yes ANO	Yes ANO	Yes No	
Pump Tank	☐Yes ☐No	☐ Yes ☐ No	□Yes □No	
	Yes No	☐Yes ☐No	[] Yes []No	
6. How many gallons of septage were remov	ed?			
Tank#1 1000 Tank#2 1000	Pretreatment Tan	kPui	np Tank	
7. Other information: List any troubleshooting	g, minor repairs condu	sted, tank safety concer	ns, or other concerns,	
3. Certification: I hereby certify as a State of Mi and made the observations, or	Thesas continue services	than b		
and made the observations, or	directly supervised other	aintainer that I personally is in the performance of the	conducted the work	
Maintainer's Name: Olson's Sewer Service, Inc		Address: 17638 Lyons St		
Maintainer's License #: 216 Maintain	er's Phone #: 651-464-2	082	- CONTRACTOR OF THE PROPERTY O	
Maintainer's Signature		Date: 41/5	~/	
VII				