

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must b	e completed in its entirety	y to constitute a v	alid maintenance r	permit. This permit m	oust be sempleded	
prior to perio	orning maintenance activi	ities and remain o	n-site for the dura	tion of the maintenan	ce activity	
Date of Maintenance	: Reason	n for Maintenance:	Routine	,		
Property Address: _	0600 Kelvin Au	e N	Property Owner's N	Name: Pat O.00	davando	
Municipality: Sty	water zip: 55	087_Property Id	entification Number	:	sgrange	
Maintenance Permit	No: <u>C856707238</u>	Maintainer Name :	and License No. Binl	ada Fasiona de La	_	
		Tame (	and License No. Fill	ky's Environmental Sev	ver Service/ L1673	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		CONTRACTOR AND ADDRESS OF THE PARTY OF THE P	Liquid Level of Tank — in			
Sludge and scum measured			Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?			Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		A THE RESERVE OF THE PARTY OF T	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rea	move sentage: Maintona			nast be pumped in	23% or greater	
Were all covers so	move septage: Maintena	The Hote Ditner	enter authorization co	ode) Twkh L	of deply	
	carety replaced: 165	□ NO				
ovidence of dam	of tank leakage from a sep	otic, holding, pret	reatment or pump	tank below the opera	ting depth or	
evidence or dame	aged, cracked, or structur	ally unsound mair	ntenance hole cove	rs? 🗌 Yes 🗆 No		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
. How many gallons	of septage were removed?					
Tank #1 1250	gal Tank #2	gal Pretreatment	tank ga	l Pump Tank	T	
. Other information:	List any troubleshooting,	minor repairs co	nducted tank safet	CV CONCORNS or other	gat	
			radica, came saret	y concerns, or other	concerns.	
		,				
. Location of septage	disposal:	Pm				
	Pinkv's	Environmental Se	wer Service Inc			
		PO Box 35				
		10 000 33				

Afton MN 55001

Maintenance activities must be reported to the Department within 90 days.