

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be complete					
prior to perfor	ming maintenance activitie	es and remain on	site for the duration	on of the maintenan	ce activity.
Date of Maintenance:	9-13-16 Reason fo	or Maintenance:	Koutine	2 Mainte	nance
Property Address: 3	of Robert Stra	energy company of the		ame: Tammy	Neuxo
Municipality:	croix IP:550	Property Ider	ntification Number:		
Maintenance Permit No	:99455u4079 M	aintainer Name ar	d License No. Ron's	s Sewer Service/ L21	03
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
<ol> <li>Were all covers see</li> <li>Is there evidence of</li> </ol>	nove septage: A Maintenand curely replaced? A Yes C of tank leakage from a sept ged, cracked, or structura	☐ No ic, holding, pretr	eatment or pump	tank below the oper	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	□ Yes ♣\No	☐ Yes #TNo	☐ Yes ♣No	
	Septic/Holding Tank #2	☐ Yes ♣ No	☐ Yes ∰No	□ Yes ⊅No	
	Pretreatment Tank	☐ Yes ☐ No	$\square$ Yes $\square$ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes No	□ Yes ↓ No	☐ Yes ∯No	
4. How many gallons	of septage were removed?	,			
Tank #1 /000 gal Tank #2 /000 gal Pretreatment tank gal Pump Tank					gal
	List any troubleshooting,				er concerns.
6. Location of septage	disposal:			,	