

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety				
<u>prior</u> to perforr	ning maintenance activiti	es and remain on-	site for the dura	tion of the maintenance	e activity.
Date of Maintenance:	7-29-16 Reason	for Maintenance:	Soutic	ell lain	Tenan
Property Address: 52	LoT Jerome Ave	eCTN P	roperty Owner's I	Name: Veil Of	pottor
	Elmo ZIP:550				
Maintenance Permit No	:V807923304 N	laintainer Name an	d License No. Ror	i's Sewer Service/ L210	3
Maintenan	ce Performed	Tank Meas	urement (must b	e completed if tanks N	OT pumped)
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers sec	ove septage: Maintenai urely replaced? Yes f tank leakage from a sep ged, cracked, or structura	□ No otic, holding, pretr	eatment or pump	o tank below the opera	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	,
	Septic/Holding Tank #1	☐ Yes ♠No	☐ Yes Æ No	☐ Yes 🍂 No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 /250 gal Tank #2		gal Pretreatmen	tank	gal Pump Tank	gal
	List any troubleshooting	_ , minor repairs co	nducted, tank sa	fety concerns, or othe	r concerns.
6. Location of septage					