

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:11/28/	2023 Reason for Mainter	nance: Routine	
Property Address: 2570 Bailey	Ct Newport, MN	Property Owner's Name:	Dewain Goff
Municipality:	ZIP: <u>55055</u> Prop	erty Identification Number:	
Maintenance Permit No: Maintaine		Name and License No. Schlomka Serv	vice LLC/L2989

Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)		
 Tank(s) Pumped Sludge and scum measured Do tanks need to be pumped? Yes No (if no provide measurements) 	Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater		

1. Access used to remove septage:
Maintenance Hole Other (enter authorization code)

- 2. Were all covers securely replaced? Tes No N/A
- 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? <u>No couldn't confirm precast vis</u> No - couldn't confirm precast via camera

Tank	Leaking Out	Leaking In	Cover Damage
Septic/Holding Tank #1	Some answers un	Ves No known. Pumped thro	Yes No-
Septic/Holding Tank #2	- I Yes I No	- Yes No	- Yes No-
Pretreatment Tank	□ Yes □No	□ Yes □No	□ Yes □No
Pump Tank	🗆 Yes 🗌 No	□ Yes □No	□ Yes □No

4. How many gallons of septage were removed?

Tank #1<u>1500</u> gal Tank #2 _____ gal Pretreatment tank _____ gal Pump Tank _____ gal

5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.

Some answers unknown. Pumped through inspection pipe.

Location of septage disposal: Metro MCES WWTP

Schlomka Services, LLC 17560 Northfield BLVD Hastings, MN 55033 License# 2989 P: 651-459-3718

Maintenance activities must be reported to the Department within 90 days.