GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 12-1-23	Reason for Maintena	nce: V 2017-	10.220	
Property Address: 14676 10	C 1 C 13000	1-201	11133 161°	
Municipality:		- riopeny Owner's Nam	ne: terri Volkenant	
	State MN	Zip Code 55 × 1	GEO Code/Property ID &	
e a Victivary one (streng) (TO CAMPAGE AND ADDRESS OF THE PARTY OF THE P	Osomila da	
☐ Tank(s) Pumped	Property of the second of the		the double fall of the fall of	
Sludge and scum measured.	Liquid Leve	el of Tafik in. Si	ludge Level in. Scum Level	
Do tanks need to be pumped? Yes No life a provide many	utements) Total (Sludg	t:		in.
- 1.0 (ii no provide nieds)	- Cincina)		id Level = %Sludge & Scum	1
T. Access used to remove septage:	Maintenance Hole [] C	ther (Go to #3 below)	* Tank must be pumped if this val	_
2. If maintenance hole was used, were all	covers securely replace	DIVES TING PLANS	is greater than 25%.	le
explanation:		/		
3. If owner refuses to allow a Subsurface them complete and sign the following	Sewage Transmand C			
them complete and sign the following	statement:	stem (SSTS) to be pump	ed through the maintenance hole, have	25
l, ·	(aumorla)	•		
hole. I understand that removal of solids 4. Is the tank designed as a leaky tank? exam	and liquids through out	e to allow the removal of s	olids and liquids through the maintenance	
4. Is the tank designed as a leaky tank? exam	nple: seepage pit, cesspor	of drawell leaching at	sidered maintenance,	
Tank#1 ☐ Yes ☐ No Verificatio Met	hod Used	a dry well, leaching pit		
Tanking Processing	<i>i</i>			
5. Is there evidence of such that	nod Used:	2		
5. Is there evidence of tank leakage from a damaged, cracked, or structurally unsou	septic, holding, pretre	eatment or pump tank be	low the operating death and	
Tank	Leaking Out	1	e are surjected of exidence of	
Septic/Holding Tank#1	Yes No	Leaking In	Cover Damage	
Septic/Holding Tank #2	Yes No	Yes No	Yes ON	
Pretreatment Tank	☐Yes ☐No	Yes Divo	Yes No	
Pump Tank	Yes VINO	Yes No	☐ Yes ☐ No	
5. How many gallons of septage were remov	ed?	Thes Alvo	Li Yes No	
Tank#1 350 Tank#2 1350				
(0.3	Pretreatment Ta	nk Pur	np Tank 350	
. Other information: List any troubleshootin	g, minor repairs condu	cted, tank safety concer	ns, or other concerns	
Certification: I hereby certify as a State of Mi and made the observations, or	nnesota certified SSTS N	laintainer that I personally	Conducted the work	
Maintainer's Name: Olson's Sewer Service, Inc	^	and the benomistice of fi	pis job.	
	Maintainer's	s Address: 17638 Lyons St	reet NE, Forest Lake, MN	
Maintainer's License #: 216 Maintain	er's Phone #: 651-464-2			
Maintainer's Signature	W -		1 0 7	
	\	Date: 12	1.72	