

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: 1130/2023 Reason Property Address: 12564 600 Nicw Municipality: white Bearla Feezip: 55	n for Maintenance: 人へてN	Reg Property Owner's N	Name: Ed Fasi	n'in ghave
Municipality: white BearLakezip: 55	10 Property Ide	entification Number	:	2
Maintenance Permit No: p6390p33713	Maintainer Name a	nd License No. Smi	lie's Sewer Service/L	_2428
Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)			
 □ Tank(s) Pumped □ Sludge and scum measured □ Do tanks need to be pumped? □ Yes □ No (if no provide measurements) 	Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
 2. Were all covers securely replaced? Yes 3. Is there evidence of tank leakage from a sere evidence of damaged, cracked, or structure Tank	ptic, holding, pret	reatment or pump tenance hole cove Leaking In	tank below the opeers? Yes Ho	rating depth or
Septic/Holding Tank #1	☐ Yes No	MILLER TO THE PARTY OF THE PART	☐ Yes ☐ No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
 4. How many gallons of septage were removed Tank #1	_ gal Pretreatmen	t tank g nducted, tank safe	al Pump Tank ty concerns, or othe	gal er concerns.
6. Location of septage disposal:				

Smilie's Sewer Service PO BOX 100 Scandia, MN 55073 License# 2428 P: 651-433-3934