

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity

Date (1) 10 10 10 23			tion of the maintena	ince activity.	
Date of Maintenance: 13/13/3633 Reas	son for Maintenance:	Reg			
Property Address: 10308 Kerry (L		Property Owner's N	Name: Stewe T	195:50	
Municipality: Hugo ZIP: 5	5038 Property Ide	ntification Number	:		
Maintenance Permit No: 19107 45586			lie's Sewer Service/L	2.420	
1 10 10 10	_ Manicaniei Haine ai	id License No. 31111	tie 3 Sewer Service/ L	2428	
Maintenance Performed	Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum _	Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
\square Yes \square No (if no provide measuremen	ts) = % Sludge & Sci	um Ta	inks must be pumped	if 25% or greater	
4					
No. of the last of	enance Hole Other (e	enter authorization c	ode)		
2. Were all covers securely replaced? Ye					
3. Is there evidence of tank leakage from a	septic, holding, pretr	eatment or pump	tank below the ope	rating depth or	
evidence of damaged, cracked, or struc	turally unsound main	tenance hole cove	ers? 🗌 Yes 🖹 No		
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes No	☐ Yes No	☐ Yes No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were remov					
Tank #1 gal Tank #2	gal Pretreatment	tank g	al Pump Tank	gal	
5. Other information: List any troubleshooti	ng, minor repairs cor	nducted, tank safe	ety concerns, or other	er concerns.	
1 cm A	χ.Λο				
6. Location of septage disposal:	AH				

Smilie's Sewer Service PO BOX 100 Scandia, MN 55073 License# 2428 P: 651-433-3934