

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	Reason	for Maintenance:	clausens		
Property Address: 100	30 14th SI N	F	Property Owner's N	ame: Jayrod + He	eather Main
	ZIP: <u>650</u>				
	0: b 9606 w 33708				
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped Sludge and scum measured Do tanks need to be pumped? Yes \(\sum \) No (if no provide measurements)		Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers se3. Is there evidence of	nove septage: Maintena curely replaced? Yes of tank leakage from a sep aged, cracked, or structur	☐ No otic, holding, preti	reatment or pump	tank below the ope	rating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ►No	☐ Yes ►No	Yes XNo	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1 1200	of septage were removed _ gal Tank #2 : List any troubleshooting	_ gal Pretreatmen			
6. Location of septage	e disposal:				

Smilie's Sewer Service PO BOX 100 Scandia, MN 55073

License# 2428 P: 651-433-3934