

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety to	o constitute a val	id maintenance pe	rmit. This permit m	ust be complete
prior to perform	ning maintenance activitie	es and remain on-	site for the durati	on of the maintenance	ce activity.
Date of Maintenance: _	9-16-16 Reason fo	1		Mainte	marce
Property Address:	956 alstst	. N . P	roperty Owner's Na	ame: Kristin	e Omi-
Municipality: W	Veland TIPETAL	2 Property Ider	tification Number:		
1				A SA SAN COLORES SILVERS	
Maintenance Permit No	» C80H01FC0G:	aintainer Name an	d License No. Ron'	s Sewer Service/ L210	13
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
<ul><li>2. Were all covers sec</li><li>3. Is there evidence of</li></ul>	curely replaced? Y Yes Confident tank leakage from a septiged, cracked, or structura	□ No cic, holding, pretr	eatment or pump	tank below the opera	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes No	☐ Yes ♣No	☐ Yes ĀNo	
	Septic/Holding Tank #2	☐ Yes No	☐ Yes ∯No	☐ Yes #No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes TNo	☐ Yes No	☐ Yes No	
4. How many gallons	of septage were removed?	•			
Tank #1 1000 gal Tank #2 1000 gal Pretreatment tank gal Pump Tank gal					
5. Other information	: List any troubleshooting,	minor repairs co	nducted, tank safe	ety concerns, or othe	er concerns.
6. Location of septage	12				