

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety i ming maintenance activiti				
Date of Maintenance:	0//	for Maintenance:	11	16	nee detivity.
Property Address: 52	//	1	Property Owner's N	ame: Jan Co	Misce
Municipality://	JSO ZIP:		ntification Number:		
Maintenance Permit N	0: <u>66643w3954</u> M		nd License No. Smi	lie's Sewer Service/I	_2428
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
\square Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence o	curely replaced? X Yes C of tank leakage from a sept ged, cracked, or structura	ic, holding, preto Ily unsound main	reatment or pump tenance hole cove	tank below the oper	rating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes No	☐ Yes No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☑No	☐ Yes No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes 💆 No	☐ Yes 🗓 No	☐ Yes ☐ Ño	
4. How many gallons	of septage were removed?				
Tank #1 153	gal Tank #2 1050	gal Pretreatmen	t tankga	al Pump Tank 🃝	්ට gal
5. Other information:	List any troubleshooting,	minor repairs co	nducted, tank safe	ty concerns, or othe	er concerns.
	(P)				
6. Location of septage					: