

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be o	completed in its entirety	to constitute a va	lid maintenance pe	ermit. This permit	must be completed	
<u>prior</u> to perform	ming maintenance activit	ies and remain on	-site for the durati	on of the maintena	ince activity.	
Date of Maintenance: _	9-2-16 Reason	for Maintenance:	Cleaning			
Property Address: 29	135 Jamley Ave	N	Property Owner's Na	ame: Chuck	Priefer	
Municipality: La Ke	Elmo ZIP: 550	04み Property Ide	ntification Number:			
	: e9292c3974 M					
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
$\square$ Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
Yes No (if no provide measurements)		= % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater			
<ol> <li>Were all covers sec</li> <li>Is there evidence o</li> </ol>	ove septage: Maintenan urely replaced? Yes f tank leakage from a sep ged, cracked, or structur	□ No	eatment or pump	tank below the ope	erating depth or	
_	Tank	Leaking Out	Leaking In	Cover Damage	_	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐No	☐ Yes ☐No	_	
4. How many gallons of	of septage were removed	?				
Tank #1 1000	gal Tank #2	gal Pretreatmen	t tankga	al Pump Tank3	OO gal	
	List any troubleshooting			1900	er concerns.	
6. Location of septage	disposal:					